
## FORWARD SKIRT ASSEMBLY

I --- INTERFACE RING ASSEMBLY 2--- SKIN SEGMENT ASSEMBLY (12 PLS)

3 — INTERCOSTAL INSTL. (19 PLS.) 4 — CHANNEL RING ASSEMBLY 5 — "U" RING ASSEMBLY

6-STRUT INSTL.

DEFFECTIVE ON "T" UNIT, SA 501 & ON



NOTE: THIS ILLUSTRATION WAS DRAWN FROM INCOMPLETE INFORMATION AND WILL BE REVISED AS ADDITIONAL ENGINEERING BECOMES AVAILABLE.

Scan of the original 1962 document courtesy of E.R.Jenne April 2021

www.edjenne.com

PROPRIETARY DATA

'THE INFORMATION AND DATA CONTAINED HEREIN IS PROPRIETARY TO THE BOEING COMPANY, AND CANNOT BE USED BY ANY OTHER PERSON, COMPANY OR AGENCY WITHOUT THE WRITTEN CONSENT OF BOEING."

| RELT     |    | PRODUCTION ILLUSTRATION REVISION NOTICE | DWN.BY | CHKD.BY | 2004 | Arru. Br | BOEINE<br>WICHITA I, KANSA | GROUP PR              | ODUC1            | TION           | ILLUSTRATION D3-4      | 1516           |
|----------|----|---|--------|---------|------|----------|----------------------------|-----------------------|------------------|----------------|------------------------|----------------|
| DA       | TE | (1) REVISED PER LATEST ENGINEERING      | VALEDY | 1       | Wen  | NES      |                            |                       | 8-1-62           | SATURN<br>S-IC | FORWARD SKIRT ASSEMBLY | SOURCE<br>ENG. |
| Clark Co | 4  |   | KEI    | 1 0     | 5    | BAR      | SUPERVISED BY              | CHRISTOPHER<br>BARNES | 8-2-62<br>8-2-62 | P.I            | 523-1106               | PAGE           |

CHG.